



Module 29112

SMAW – Open-Root Groove Welds (Plate)

Welding 29112 SMAW – Open-Root Groove Welds (Plate)



2.0.0 Open-Root Single V-Groove Welds

Objective

Successful completion of this module prepares you to do the following:

Summarize techniques for making open-root single V-groove welds.

- a. Describe producing the root pass for open-root single V-groove welds.
- b. Describe making open-root single V-groove welds in the 1G and 2G positions.
- c. Describe making open-root single V-groove welds in the 3G and 4G positions.

Performance Tasks

Under supervision, you should be able to do the following:


2. Use E6010/E6011 and E7018 electrodes to make flat (1G) open-root single V-groove welds.
3. Use E6010/E6011 and E7018 electrodes to make horizontal (2G) open-root single V-groove welds.
4. Use E6010/E6011 and E7018 electrodes to make vertical (3G) open-root single V-groove welds.
5. Use E6010/E6011 and E7018 electrodes to make overhead (4G) open-root single V-groove welds.

Trade Terms

There are no trade terms in this section.

2.0.0 – Open-Root Single V-Groove Welds

- Make groove welds with slight face reinforcement and a gradual transition to the base metal at each toe.
- Groove welds must not have excessive reinforcement (face or root), underfill, or overlap.



2.1.0 – Producing the Root Pass (1 of 4)

- Producing the root pass is the most challenging part of making an open-root single V-groove weld.
- The welder makes the root pass from the V-groove side. It must completely penetrate but not have excessive root reinforcement.
- Welders use a technique called “running a keyhole” to control penetration.
- The arc makes the keyhole by melting away the root faces (lands) of the plates.
- The molten metal flows to the back side of the keyhole, forming the weld.


2.1.0 – Producing the Root Pass (2 of 4)

- The keyhole should be centered and about $\frac{1}{8}$ " to $\frac{3}{16}$ " (~3 mm to 5 mm) in diameter.
- Root reinforcement should be either flush or no more than the code, WPS, or jobsite quality specifications permit.
- Control the keyhole by using a fast-freeze E6010/E6011 electrode and whipping it.
- Carefully watch the keyhole's back edge to ensure good fusion. This area should be round. If it becomes V-shaped, proper fusion isn't happening.
- If the keyhole starts to grow, reduce the pause time and increase the whip's forward length.

2.1.0 – Producing the Root Pass (3 of 4)

- If the keyhole starts to close, increase the pause time and decrease the whip's forward length.
- After running the root pass, clean and inspect it.
- Remove excessive buildup or undercut with a hand grinder.
- Grind the root pass face with the grinding disc's edge.
- Don't grind through the root pass or widen the groove.

2.1.0 – Producing the Root Pass (4 of 4)



2.2.1 – Practicing Open-Root Single V-Groove Welds (1G Position) (1 of 2)


Follow these steps to practice making open-root single V-groove welds in the 1G position:

- Step 1** Tack weld the practice coupon.
- Step 2** Clean and feather (taper) the tack welds with the edge of a grinding disc. Feathering the tack welds helps fuse them into the root pass.
- Step 3** Position the practice coupon flat on the welding table.
- Step 4** Run the root pass using E6010/E6011 electrodes.
- Step 5** Chip, clean, and brush the root weld. Grind if required.

2.2.1 – Practicing Open-Root Single V-Groove Welds (1G Position) (2 of 2)

Step 6 Run the fill and cover passes using E7018 electrodes. Chip, clean, and brush each bead. Use stringer or weave beads as your instructor directs.

Step 7 When you're finished welding, *always* remove the electrode from its holder. This prevents arcing. Discard the stub in the proper container.



2.2.2 – Practicing Open-Root Single V-Groove Welds 2G Positions (1 of 5)

- Before you try this weld, practice running horizontal stringer beads.
- Do this by building a pad in the horizontal position.
- Follow these steps to practice making horizontal stringer beads in the 2G position:

Step 1 Tack weld a flat plate coupon in the horizontal position.

Step 2 Run the first pass along the coupon's bottom edge. Use E6010/E6011 electrodes.

2.2.2 – Practicing Open-Root Single V-Groove Welds 2G Positions (2 of 5)

Step 3 Chip, clean, and brush the weld.

Step 4 Weld the second bead just above the first bead. The beads should overlap as the figure below shows. Chip, clean, and brush it.


Step 5 Continue running beads until you complete the pad.



2.2.2 – Practicing Open-Root Single V-Groove Welds 2G Positions (3 of 5)

Follow these steps to practice making open-root single V-groove welds in the 2G position:

Step 1 Tack weld the practice coupon. Use the standard or alternative coupon preparation as your instructor directs.




2.2.2 – Practicing Open-Root Single V-Groove Welds 2G Positions (4 of 5)

- Step 2** Clean and feather (taper) the tack welds with the edge of a grinding disc. Feathering the tack welds helps fuse them into the root pass.
- Step 3** Tack weld the practice coupon in the horizontal position.
- Step 4** Run the root pass using E6010/E6011 electrodes.
- Step 5** Chip, clean, and brush the weld.


2.2.2 – Practicing Open-Root Single V-Groove Welds 2G Positions (5 of 5)

Step 6 Run the fill and cover passes using E7018 electrodes. Chip, clean, and brush each bead.

Step 7 When you're finished welding, *always* remove the electrode from its holder. This prevents arcing. Discard the stub in the proper container.



Note: The actual number of weld beads will vary depending on the plate thickness and electrode diameter.



Note: Nonzero work angles are approximate.

2.3.1 – Practicing Open-Root Single V-Groove Welds 3G Position (1 of 4)

- Practice running vertical weave beads.
- Do this by building a pad in the vertical position.
- Use a 0- to 10-degree push angle.
- Follow these steps to practice making vertical weave beads in the 3G position:

Step 1 Tack weld a flat plate coupon in the vertical position.

Step 2 Using a whipping motion, run the first pass along one of the coupon's vertical edges from bottom to top. Use E6010/E6011 electrodes.

2.3.1 – Practicing Open-Root Single V-Groove Welds 3G Position (2 of 4)

- Step 3** Chip, clean, and brush the weld.
- Step 4** Weld the second bead next to the first bead. The beads should overlap. Chip, clean, and brush it.
- Step 5** Continue running beads until you complete the pad.

2.3.1 – Practicing Open-Root Single V-Groove Welds 3G Position (3 of 4)


Follow these steps to practice making open-root single V-groove welds in the 3G position:

- Step 1** Tack weld the practice coupon.
- Step 2** Clean and feather (taper) the tack welds with the edge of a grinding disc. Feathering the tack welds helps fuse them into the root pass.
- Step 3** Tack weld the practice coupon in the vertical position.
- Step 4** Run the root pass as a stringer bead using E6010/E6011 electrodes from bottom to top (uphill progression).
- Step 5** Chip, clean, and brush the weld.

2.3.1 – Practicing Open-Root Single V-Groove Welds 3G Position (4 of 4)

Step 6 Run the fill and cover passes uphill as weave beads using E7018 electrodes. Chip, clean, and brush each bead.

Step 7 When you're finished welding, *always* remove the electrode from its holder. This prevents arcing. Discard the stub in the proper container.




2.3.2 – Practicing Open-Root Single V-Groove Welds (4G Position) (1 of 4)

- Before trying open-root groove welding in the 4G position, practice building pads with overhead stringer beads.
- Follow these steps to practice making overhead stringer beads in the 4G position:
 - Step 1** Tack weld a flat plate coupon in the overhead position.
 - Step 2** Run the first pass along one of the coupon's edges. Use E6010/E6011 electrodes.
 - Step 3** Chip, clean, and brush the weld.

2.3.2 – Practicing Open-Root Single V-Groove Welds (4G Position) (2 of 4)

Step 4 Weld the second bead next to the first bead. The beads should overlap. Chip, clean, and brush it.

Step 5 Continue running beads until you complete the pad.



2.3.2 – Practicing Open-Root Single V-Groove Welds 4G Position (3 of 4)

Follow these steps to practice making open-root single V-groove welds in the 4G position:

Step 1 Tack weld the practice coupon.

Step 2 Clean and feather (taper) the tack welds with the edge of a grinding disc. Feathering the tack welds helps fuse them into the root pass.

Step 3 Tack weld the practice coupon in the overhead position.


Step 4 Run the root pass using E6010/E6011 electrodes.

Step 5 Chip, clean, and brush the weld.

2.3.2 – Practicing Open-Root Single V-Groove Welds 4G Position (4 of 4)

Step 6 Run the fill and cover passes using E7018 electrodes. Chip, clean, and brush each bead.

Step 7 When you're finished welding, *always* remove the electrode from its holder. This prevents arcing. Discard the stub in the proper container.



Stringer Bead Sequence

Note: Nonzero work angles are approximate.

2.0.0 Section Review Question One

The key to a successful root pass when welding an open-root single V-groove weld is controlling the _____.

weave

groove angle

keyhole

bevel angle

2.0.0 Section Review Question One Answer

The key to a successful root pass when welding an open-root single V-groove weld is controlling the _____.

weave

groove angle

keyhole

bevel angle

2.0.0 Section Review Question Two

When making an open-root single V-groove weld horizontally, you are welding in the _____.

1G position

2G position

3G position

4G position

2.0.0 Section Review Question Two Answer

When making an open-root single V-groove weld horizontally, you are welding in the _____.

1G position

2G position

3G position

4G position

2.0.0 Section Review Question Three

You're producing an open-root single V-groove weld in the 3G position. Unless the applicable code, WPS, or jobsite quality specifications forbid it, what bead style should you use?

Weave beads

Root face beads

Stringer beads

Keyhole beads

2.0.0 Section Review Question Three Answer

You're producing an open-root single V-groove weld in the 3G position. Unless the applicable code, WPS, or jobsite quality specifications forbid it, what bead style should you use?

Weave beads

Root face beads

Stringer beads

Keyhole beads

Welding 29112 SMAW – Open-Root Groove Welds (Plate)



Next...

Module Review and Exam

Review the complete module to prepare for the Module Exam. In addition, complete the Module Review.